Central Shippee, Inc. **Material Safety Data Sheet**

1. PRODUCT AND COMPANY IDENTIFICATION

DURAFELT, Non-woven FELT Product name:

Company Information: Central Shippee, Inc.

46 Star Lake Road

Bloomingdale, NJ 07403 United States of America

973-838-1100

Emergency Telephone: Chemtrec 1-800-424-9300

2. COMPOSITION / INFORMATION ON INGREDIENTS

Components: CAS No. Average Concentration Units Concentration Range

***this material may be Polyester Fiber Web 25038-59-9 Acrylic fiber N/A 100% PET, 100% Acrylic or Minor Pigments – Additives a blend depending on N/A availability or fiber and / or customer specifications.

This material is an "Article" and is considered non-hazardous per the OSHA Hazard Communication Standard 29-CFR 1910.1200.

3. PHYSICAL / CHEMICAL CHARACTERISTICS

Boiling Point NA Specific Gravity NA Vapor Pressures (mm Hg) NA Melting Point 258 C Vapor Density (Air=1) NA **Evaporation Rate** NA Solubility in water Insoluble

Appearance and Odor Non-woven fiber web, adhesive backing, no distinct

odor.

4. FIRE AND EXPLOSION HAZARD DATA

Flash point NA Combustible Solid LEL NA UEL NA

Extinguishing media: Water fog, foam Dry (ABC)

Fire Fighting Procedures: Use full bunker gear including NIOSH approved

breathing apparatus.

Unusual Fire and Explosion hazards: None known. Treat as solid that burns

generally with low smoke density.

5. REACTIVITY DATA

Stability: Stable No known conditions to avoid

Incompatibility Strong Oxidizing Agents

Hazardous Decomposition or By Products CO, CO₂, and small amounts of

aliphatic and aromatic hydrocarbons.

Hazardous Polymerizaton Will NOT Occur No known conditions to avoid

6. HEALTH HAZARD DATA

Routes of entry Inhalation – NA Skin – NA Ingestion – NA

Health Hazards None Known

Carcinogenicity NTP-NA IARC monograph-NA OSHA Regulated-NA Signs and Symptoms of Exposure Fine dust may cause mechanical irritation.

Medical Conditions Generally Aggravated by Exposure

Pre-existing eye and respiratory disorders may be aggravated by

product dust.

Emergency and First Aid Procedures

Flush eyes with water for at least 10 minutes.

Contact with molten material should be treated as a thermal burn. Seek medical attention for all burns, particularly if in the facial

area.

7. PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to be taken in case material is released or spilled

Shovel, sweep or vacuum. Avoid generating dust clouds

Waste Disposal Method

Place in appropriate container and dispose of on compliance with all

Federal, State and Local ordinances.

Precautions to be taken in Handling and Storing

Treat as a solid that can burn.

Other Precautions

Store away from oxidizing agents

8. CONTROL MEASURES

Respiratory Protection

NOT Required. Appropriate dust mask can be used if dust is present.

Ventilation Mechanical (general) – Recommended

Protective Gloves NOT Required.
Other Protective Clothing NOT Required.

Eye Protection ANSI Z87 safety glasses recommended World / Hygienic Practices Use good hygienic practices and procedures.

While the information and recommendation set forth in this Material Safety Data Sheet are presented in good faith and believed to be as correct as of the date presented, Central / Shippee, Inc. makes no representation as to the completeness or accuracy. Information is supplied on the condition that the persons receiving this information will make their own determination as to its suitability for their purposes prior to use. In no event will Central / Shippee, Inc. be responsible for damages of any nature whatsoever resulting from the use of or reliance upon the information. NO REPRESENTATION OR WARRANTIES, EITHER EXPRESS OR IMPLIED, OF MERCHANTABLILITY, FITNESS FOR A PARTICULAR PURPOSE OR ANY OTHER NATURES ARE MADE HEREUNDER WITH RESPECT TO INFORMATION OR THE PRODUCT TO WHICH INFORMATION REFERS.